



## Photographic Log


<b>Client Name:</b> Robert Manseau		<b>Site Location:</b> 54 Lake Attitash Road Amesbury, Massachusetts	<b>Project No.</b> 01.0175290.00
<b>Photo No.</b> 1	<b>Date:</b> 8/17/21		
<b>Direction Photo Taken:</b> Northwest			
<b>Description:</b> View looking along shoreline to the north of the dock, note stone wall along toe of slope. Also note wood stairs to dock.			

<b>Photo No.</b> 2	<b>Date:</b> 8/17/21	
<b>Direction Photo Taken:</b> Southeast		
<b>Description:</b> View looking along shoreline to the south of the dock, note stone wall along toe of slope. Also note wood stairs to dock.		





## Photographic Log


<b>Client Name:</b> Robert Manseau		<b>Site Location:</b> 54 Lake Attitash Road Amesbury, Massachusetts	<b>Project No.</b> 01.0175290.00
<b>Photo No.</b> 3	<b>Date:</b> 8/17/21	 A vertical photograph showing a stone wall along a slope. The wall is made of large, dark stones. In the foreground, there are green plants and yellow flowers. In the background, there are trees and a building.	
<b>Direction Photo Taken:</b> Northwest			
<b>Description:</b> View along toe of slope. Note stone wall in fore and midground. Also note several stones have fallen from the wall.			

<b>Photo No.</b> 4	<b>Date:</b> 8/17/21	 A horizontal photograph showing a stone wall along a slope. The wall is made of large, dark stones. In the foreground, there are green plants and yellow flowers. In the background, there are trees and a building.
<b>Direction Photo Taken:</b> South		
<b>Description:</b> View along toe of slope showing stone wall.		





## Photographic Log

<b>Client Name:</b> Robert Manseau		<b>Site Location:</b> 54 Lake Attitash Road Amesbury, Massachusetts	<b>Project No.</b> 01.0175290.00
<b>Photo No.</b> 5	<b>Date:</b> 8/17/21		
<b>Direction Photo Taken:</b> East			
<b>Description:</b> View towards Lake Attitash Road and area of proposed pervious paver installation.			

<b>Photo No.</b> 6	<b>Date:</b> 8/17/21	
<b>Direction Photo Taken:</b> West		
<b>Description:</b> View facing edge of proposed pervious paver installation and proposed pervious paver walkway towards stairs to dock.		